

Sign Guidance by Map Number, Minute Man National Historical Park, December 2025 Draft

Generally West to East within Concord

Note: Some signs will not be fabricated or installed as indicated by “None.”

Plan #	Sign(s)	Fabricate	Install	GPS points using town GIS websites: Latitude, Longitude	Location Instructions
1	None	-	-	-	-(Highway signs not included in contract)
2	None	-	-	-	-
3	PF-1.1D-21, PF-1.1D-22; PF-2.1D-1, PF-2.1D-2	F			Contract Option 1: Fabricate and deliver. Signs will be placed in park storage.
3	PLRS-2.0-1, PLRS-3.0-1	F			Contract Option 1: Fabricate and deliver. Signs will be placed in park storage.
3	INFO-M-1	F			Contract Option 1: Fabricate without “you are here” in map and deliver. Sign will be placed in park storage. Add “you are here” sticker when sign is installed.
3	PD-1	n/a	n/a	42.47353, -71.38040	Replaced with “Private Residence” and sign is installed.
4	None	-	-	-	Pathfinder signs in front of private properties. (Do not manufacture or install the two signs on this map: RG-1.0-8, RG-2.0-11) at this time.

5	PF-2.0D-1	F	I	42.46705, -71.35746	“NBVC” Install 150 feet west of RG-2.0-9 on backside of guardrail. Adjacent landowner is Concord Land Conservation Trust.
5	PF-2.0D-2	F	I	42.4695, -71.35618	“NBVC” Install 200 feet east of crosswalk and 100 feet of town sign, “No Parking Here to Corner.” Install on back side of guardrail and six inches from guardrail. Adjacent to 288 Lowell Road, owned by John Bemis.
5	RG-2.0-9	F	I	42.46699, -71.35717	See Attachment U from Harper’s Ferry for correct wording. ←Concord Center Battle Road Barrett House→ Destinations and arrows sign that is parallel to Lowell Road, visible from Liberty Street, centered on painted centerline of Liberty St. Install on southwest side of Lowell Road, back side of guardrail. Replace existing signs in location.
6	AP-1.0-1	F	I	42.47128, -71.35319	Accessible parking NBVC lot. Southeast of sidewalk? The park has 2 accessible spaces, but sign plan recommends three. How about proceed with two until repaved and restriped?
6	AP-1.0-2	F	I	42.47123, -71.35320	Southeast of sidewalk? Includes second sign “Van Accessible”
6	AP-1.0-24	F	maybe		Southeast of sidewalk? This space does not exist?
6	DOT1.0-1		I	42.47107, -71.35356	Do not enter sign. Replace in kind and in proximate location – parallel to Liberty Street, outside corner of stone wall caps.
6	DOT1.0-2		I	42.47100, -71.35350	Do not enter sign. Replace in kind and in proximate location – parallel to Liberty Street, outside corner of stone wall caps.

6	DOT3.0-1		I	42.47109, -71.35352	Stop sign at exit of NBVC parking lot. On same post, install “Do Not Enter” sign on northwest side of exit on back of sunset sign.
6	INFO-M-2	F	I	42.47084, -71.35272	Info sign. Replace existing info bulletin board in location near NBVC entrance.
6	PF-3.1D-4	F	I	42.47113, -71.35366	NBVC – narrow space between wall and road. Install on park side of stone wall one hundred feet beyond parking lot exit.
6	TD-M-1	F	I	42.47060, -71.35310	Direction to North Bridge. Describe orientation and whether one or two sided. North of intersection of North Bridge Trail and asphalt path to North Bridge Visitor Center. Orient perpendicular to North Bridge Trail and parallel to asphalt path.
6	TD-M-15	F	I	42.47081, -71.35275	Direction to North Bridge. Describe orientation and whether one or two sided. Located at intersection of Entrance circle and asphalt path. Orient parallel to circle edge and perpendicular to asphalt path at southeast side of path.
7	DOT1.0-19		I	42.47214, -71.35293	Do not enter for vehicles leaving lot, northeast side of drive.
7	DOT1.0-20		I	42.47211, -71.35303	Do not enter for vehicles leaving lot, southwest side of drive. Mount sunset sign, PLRS-2.0-2 on back side.
7	DOT2.0-1		I	42.47166, -71.35335	One way, replace in kind in location
7	DOT2.0-2		I	42.47162, -71.35311	One way, replace in kind in location
7	PF-3.1D-1 and PF-3.1D-2	F	I	42.47227, -71.35317	Back-to-back (2-sided) on one post, just west of existing double sided sign (across from entry apron). Remove existing sign,

7	PF-3.1D-3	No	No	n/a	Guidance to NBVC. Do not manufacture or install due to proximity to private residence
7	PLRS-2.0-2	F	I	42.47216, -71.35309	“Sunset” Put in same location as existing and on same post as DOT1.0-20 (do not enter). Install “do not enter” on back side.
7	RG-2.0-12	No	No	n/a	Guidance to Barrett, but poorly placed. Do not manufacture or install due to traffic flow from NBVC exit to Liberty Street to Lowell Road, sign is not visible to visitors exiting NBVC.
8	PF-2.0D-3 and PF-2,0D-4	F	I	42.47327, -71.35106	Back-to-back (2-sided) on one post for NBVC. Remove existing sign. The park will confirm letter size and sign size with Town of Concord.
9	PF-1.1D-20	F	I	42.47081, -71.34964	“parking ahead.” Eastbound on Monument Street just after bridge and one hundred feet past yellow warning sign for upcoming crosswalk sign. Install on backside of guardrail, southwest side of road.
10	ADA-1, 2, 3	F	I	42.46949, -71.34905	Building address: 313 Monument Street, affix signs to comfort station
10	AP-1.0-3	F	I	42.46950, -71.34871	Accessible parking. Place in lawn strip, midway between parking and stone wall
10	AP-1.0-4	F	I	42.46944, -71.34867	Accessible parking plus “Van accessible” Place in lawn strip, midway between parking and stone wall
10	AP-1.0-5	F	I	42.46933, -71.34861	Accessible parking. Place in lawn strip, midway between parking and stone wall
10	AP-1.0-6	F	I	42.46929, -71.34858	Accessible parking. Place in lawn strip, midway between parking and stone wall

10	DOT1.0-3		I	42.46988, -71.34894	Do not enter. Replace in kind in location at north exit of NB lot. Place on inside of stone wall and Stop sign on back if permissible.
10	DOT1.0-4		I	42.46982, -71.34890	Do not enter. Replace in kind in location at north exit of NB lot.
10	DOT1.0-5		I	42.46910, -71.34830	Do not enter at southeast one way entrance to North Bridge parking lot
10	DOT1.0-6		I	42.46912, -71.34818	Do not enter at southeast one way entrance to North Bridge parking lot – only one sign needed here. Eliminate this sign.
10	DOT2.0-3		I	42.46908, -71.34834	One way sign at southern tip of tear drop island in North Bridge parking lot. Exists. Replace in kind.
10	DOT2.0-4		I	42.46904, -71.34817	One way sign at eastern edge of south one way entrance to North Bridge parking lot. This sign does not currently exist. It is not needed and might cause confusion.
10	DOT3.0-2		?	42.46989, -71.34893	Stop sign, north exit of North Bridge parking lot. Mount on back side of “Do Not Enter” sign.
10	DOT3.0-3		?	42.46910, -71.34847	Stop sign, south exit of North Bridge parking lot. Sight lines very important here. Place sign in grass strip between stone wall and parking lot. About four feet northwest of exit. Make sure fully painted with strip so that exiting vehicles do not collide with entering vehicles.
10	DOT3.1-1		I	42.46934, -71.34882	Crosswalk warning? West side of Monument Street (For pedestrians crossing east to go to the parking lot) This sign will be difficult to place.
10	DOT3.1-2		I	42.46943, -71.34867	Crosswalk warning? East side of Monument Street (For pedestrians crossing west to go to North Bridge)

10	ID-35.0	TBD	TBD	42.46905, -71.34837	North Bridge entry sign that repeats content of Facility Identity sign for eastbound travelers entering the lot behind the large North Bridge Facility Identity sign. These travelers have already passed two “North Bridge Parking” signs along Monument Street (PF-1.1D-20 and PF-2.1D-3)
10	INFO-M-3	F		42.46915, -71.34867	Install at location of existing bulletin board along North Bridge Trail, south of comfort station.
10	PLRS-1.0-1	F	I	42.46817, -71.34770	“Bus and RV Pkg Only, No Idling” Repeats info on proposed green and white signs (see MMVC RP-1 thru 8 signs.) If retained, install in location of current sign along western edge of parking lot teardrop island—where buses currently park.
10	PLRS-2.0-3	F	I	42.46806, -71.34773	“Sunset” Install in location of current “sunset” sign at lower south tip of parking lot teardrop island.
10	TD-L-1	F		42.46939, -71.34863	Trail direction on south side of walkway ___ feet from walkway, ___ from stone wall, ___ from tree.
10	TD-M-2	F	I	42.46881, -71.35156	Trail direction on North Bridge Trail Install at site of existing sign, ___ feet west of Isaac Davis plaque/boulder. Edge of sign should be 2 feet from trail edge.
11	PF-1.1D-19	F	I	42.46725, -71.34802	Parking Ahead. Install along Monument Street below Elisha Jones orchard, 6 feet from Monument St edge, north side of road edge and 4 feet from stone wall and 100 feet north of Ripley Hill Road intersection.
11	TD-FP-8	F	I	42.46791, -71.34884	Trail direction on post at northwest corner of Sargent Field on path through Old Manse. Install at site of existing sign, west (left) of gap in stone wall when facing north. Request access to Sargent Field, 235 Monument St (entrance has locked chain)

12	RG-2.0-1	F	I	42.46032, -71.34858	Road guidance to North Bridge, Concord Museum, Orchard House, The Wayside at Town Square Rotary. Collaborate with Town of Concord. Affix to existing sign post.
12	RG-2.0-13	F	I	42.46128, -71.34917	Road guidance with arrow plus N Bridge, Robbins House, Old Manse. Place sign in traffic island a few feet to the north in front of Colonial Inn and maybe on existing post. Collaborate with Town of Concord. (Contractor placed on the site of a No Parking sign in front of the town building.
13	RG-2.0-2	F	I	42.45859, -71.34578	Road guidance with arrows to North Bridge, Concord Museum, Orchard House, and The Wayside at the intersection of Lexington Road and Heywood Street. Collaborate with Town of Concord. Sign post remains, but sign disappeared in summer 2025. Replace sign post to match Town of Concord standard.
13	RG-1.0-1	No	No	n/a	n/a
13	RG-2.0-10	No	No	n/a	n/a
14	AP-1.0-7	F	I	42.45839, -71.33366	Place at head of accessible parking space at The Wayside parking lot, west of sidewalk in lawn edge, 2 feet from edge of sidewalk
14	AP-1.0-8	F	I	42.45836, -71.33365	Place at head of accessible parking space at The Wayside parking lot, west of sidewalk in lawn edge, 2 feet from edge of sidewalk Neither Wayside sign indicates Van accessible. Add van accessible?
14	DOT3.0-13		I	42.45781, -71.33312	Stop sign for exit of Wayside parking lot. Install on south side of exit, behind (west) of chain post

14	DOT3.1-3		?	42.45871, -71.33376	Stop sign for pedestrian crossing of Lexington Road at cross walk, south side of Lexington Road. Consider eliminating this pair of stop signs.
14	DOT3.1-4		?	42.45879, -71.33381	Stop sign for pedestrian crossing. No space for this sign on north side of Lexington Road. Consider eliminating pair of stop signs.
14	PF-2.1D-5	F	I	42.45869, -71.33386	Pathfinder for The Wayside parking lot. For eastbound travelers. Place adjacent to NPS parcel, between two telephone poles and 100 feet before crosswalk.
14	PF-2.1D-6	F	I	42.45900, -71.33260	Pathfinder for The Wayside parking lot. For westbound travelers. Place adjacent to NPS parcel, just east of barn. Replace in kind in location.
14	Add to maps PLRS-2.0-# (11)	F	I	42.45781, -71.33312	“Parking Lot Closes at Sunset” Missed by Sign Design contractor. Add to fabricate and install contract. Install on back side of DOT3.0-13 or in location of existing sign.
14	TH-S-11	Fix sign	n/a	42.45887, -71.33453	Trailhead west end of Larch Path. Need to update location of “you are here”
14	TH-S-12	Fix sign	n/a	42.45899, -71.33343	Trailhead east end of Larch Path. Need to update location of “you are here”
15	None	-	-	-	New HG at Rt 2 eastbound. Confirm with GAOA Team
16	RG-1.0-11	-	-	-	MMNHP from Rt 2 eastbound at Crosby Corner. Check in with GAOA Team
16	RG-1.0-12	-	-	-	MMNHP from Rt 2 eastbound at Crosby Corner. Check in with GAOA Team
16	RG-1.0-13	-	-	-	MMNHP from Rt 2 eastbound at Crosby Corner. Check in with GAOA Team

17	ADA-4, 5, 6	F	I	34 Old Bedford Road, Concord	Three signs. Affix to building
17	AP-1.0-9	F	I	42.45882, -71.32218	Not sure why this is in middle of parking spaces, but it is current location. Does not include van accessible. Sign Layouts indicates that AP-1.0-7 “Reserved Parking” is also at Meriams Corner parking lot, but it is not depicted on Location Plan 17.
17	DOT1.0-7	F	I	42.45873, -71.32218	Do Not enter Replace in kind in location Is one enough here? Can stop sign DOT3.0-4 be mounted on the back of this sign?
17	DOT1.0-8	F	I	42.45868, -71.32237	Do Not enter Replace in kind in location. Is one enough here? I
17	DOT1.0-16	F	I	42.45855, -71.32199	Do not enter. Replace in kind in location. Is one enough here?
17	DOT1.0-17	F	I	42.45851, -71.32185	Do not enter. Replace in kind in location
17	DOT3.0-4	F	I	42.45873, -71.32247	“Stop” Replace in kind in location. Ok to mount on back of Do Not Enter?
17	INFO-M-4	F	I	42.45871, -71.32177	Meriam lot info bulletin board. Make sure “You are here” is accurate
17	PF-1.1D-6	F	I	42.45889, -71.32328	Meriam parking. Replace in kind in location, add distance from centerline of parking lot entrance
17	PF-1.1D-7	F	I	42.45809, -71.32088	Meriam parking. Replace in kind in location
17	PF-2.1D-7	F	I	42.45851, -71.32230	Meriam parking. Replace in kind in location
17	PF-2.1D-8	F	I	42.45839, -71.32166	Meriam parking. Replace in kind in location

17	PLRS-2.0-4	F	I	42.45855, -71.32200	“Sunset” East (right) of parking lot entrance? Replace in location.
17	TD-L-28	F	I	42.45887, -71.32244	Trail direction for east and westbound travelers? 10 to 15 feet west of parking lot near split rail fence (?), north side of trail
17	TD-L-30	F	I	42.45866, -71.32169	Trail direction for east and westbound travelers? 15 to 20 feet east of parking lot near boardwalk, south side of trail
17	TD-M-14	F	I	42.45978, -71.32412	Inside of stone wall, north of spur to crosswalk, printed on both sides?
17	TH-S-19	F	I	42.46008, -71.32358	Trailhead, small. Place adjacent to building/restroom access. Need to discourage road crossing here because cross walk is on other side (south) of Meriam House
17	TS-M-1	F	I	42.45867, -71.32299	Adjacent to west post
17	TS-M-17	F	I	42.45870, -71.32140	Trail safety, walk bike. Adjacent to north side of boardwalk. Need another for the other end.
18	DOT3.0-11	No	No		“Stop” sign in place and maintained by Town of Concord.
18	TD-L-29	F	I	42.45892, -71.31346	Trail direction in field north of Carty Barn. Random location for sign, consider moving to intersection or sharp turn in the trail.
18	TS-M-18	F	I	42.45969, -71.31581	Trail safety, walk bike. West side of boardwalk, south side of trail
18	TS-M-19	F	I	42.45967, -71.31564	Trail safety, walk bike. East side of boardwalk, north side of trail

19	TD-S-7	F	I	42.45705, -71.31493	Trail direction in an area where private residences, building, and farmers. Southwest corner of 6-bay tractor open shed and split in driveway
19	TS-M-2	F	I	42.45538, -71.31292	Walk bike ahead. 200 feet east of Olive Stow Boardwalk, north side of trail, at former property corner, not sure if stone wall or marker is evident.
19	TS-M-20	F	I	42.45643, -71.31428	Walk Bike. West end of Olive Stow Boardwalk southwest side of trail
19	TS-M-21	F	I	42.45543, -71.31371	Walk Bike. East end of Olive Stow Boardwalk northeast side of trail
20	AP-1.0-10	F	I	42.45338, -71.30824	Accessible parking pad in Brooks Village parking lot
20	DOT3.0-5	F	I	42.45312, -71.30797	Stop sign at exit of Brooks Village parking lot
20	DOT3.1-7	F	I	42.45428, -71.31105	Mini stop sign at west side of Shadyside Ave on south side of Battle Road Trail
20	DOT3.1-8	F	I	42.45426, -71.31093	Mini stop sign at east side of Shadyside Ave on north side of Battle Road Trail
20	INFO-M-5	F	I	42.45334, -71.30832	“Information” at northwest corner of Brooks Village parking lot
20	PF-1.1D-8	F	I	42.45309, -71.30938	West of Brooks Village parking lot, parking lot ahead for eastbound travelers, replace in kind in location
20	PF-1.1D-9	F	I	42.45296, -71.30644	East of Brooks Village parking lot for westbound travelers, replace in kind in location
20	PF-3.1D-5	F	I	42.45300, -71.30823	Just west of Brooks Village parking lot, eastbound travelers, replace in kind in location

20	PF-3.1D-6	F	I	42.45308, -71.30776	Just east of Brooks Village parking lot, westbound travelers, replace in kind in location
20	PLRS-2.0-5	F	I	42.45313, -71.30785	“Sunset” At Brooks Village parking lot, replace in kind in location
20	TD-M-3	F	I	42.45397, -71.30812	Trail direction. At intersection of access spur from Brooks Village parking lot with Battle Road Trail, placed on north side of trail.
21	TD-M-7	F	I	42.45358, -71.30072	Trail direction. Gate at Old Bedford Road, Lincoln, replace in kind in location
21	TS-M-22	F	I	42.45353, -71.30455	Walk Bike. West end of Elm Brook Boardwalk, southeast side of trail
21	TS-M-3	F	I	42.45315, -71.30491	Walk Bike. 200 feet west of Elm Brook Boardwalk, southeast side of trail
21	TS-M-4	F	I	42.45413, -71.30265	Walk Bike. 200 feet east of Elm Brook Boardwalk, northwest side of trail
21	TS-M-8	F	I	42.45362, -71.30310	Walk Bike. East end of Elm Brook Boardwalk, where visible for westbound bicyclists