

ENVIRONMENTAL MONITOR WEEKLY REPORT
WEEK ENDING June 2, 2017

Distribution

This report was sent to the following individuals via. e-mail:

Greg Kwon, *Resident Engineer* MADOT, Greg.Kwon@dot.state.ma.us

John Viens, *Site Superintendent*, D.W. White, jviens@dwwhite.com

Delia Kaye, *Natural Resources Director*, Town of Concord, dkaye@concordma.gov

The following individuals were also CC'd via e-mail:

Mark Cain, MADOT, mark.cain@dot.state.ma.us

Tim Kelley, *Project Manager*, D.W. White, tkelley@dwwhite.com

Rich Kirby, *Environmental Monitor Team member*, LEC, RKirby@lecenvironmental.com

INSPECTIONS

There was no earthwork done during the reporting period and no rain events greater than 0.25" occurred so the Environmental Monitor did not inspect the site.

STATUS OF CONSTRUCTION

Erosion control installation is complete. Erosion control which sustained minor damage during clearing had been repaired. Clearing is complete but some brush removal remains. It is intended to complete brush removal after the tracks have been removed.

SITE SCHEDULE

It was intended to begin track removal but this work has not yet begun. When it does begin, it will start at the northernmost portion of the project and working in a southerly direction. Tree protection will begin as indicated on the plans. Regulated areas will be marked out in the field over the next two weeks.

WEATHER

The weather station at Hanscom Airfield records and publishes real-time precipitation data (USGS 01100568). According to the weather station, no events greater than 0.25" occurred during the reporting period.

ORDER OF CONDITIONS

The following conditions were met during the reporting period:

Condition 35: No staging of construction materials was taking place in the 100' buffer zone. Staging for wood chipping was being conducted off-site, behind the prison.

Condition 39: Siltation barrier has been installed and consists of, at a minimum, a 12" straw wattle. Slash vegetation has been removed from the work zone.

ENVIRONMENTAL MONITOR WEEKLY REPORT
WEEK ENDING **June 2, 2017**

Condition 47: No machinery was observed being stored in the buffer zone.

PLANNED IMPACTED AREAS

No planned wetland impact areas have been disturbed since the last reporting period.

SWPPP REPORTS

Copies of the reports are kept in the construction trailer. Copies of the report will be transmitted, once they are obtained.

SITE PHOTOGRAPHS

Site photographs were taken but nothing remarkable was observed.

GENERAL SUMMARY

No site work was conducted during the reporting period.

SUBMITTALS

SWPPP REPORTS

WEATHER REPORTS

SCHEDULE & PHASE I PLANS

PHOTOGRAPHIC DOCUMENTATION

SUBMITTAL LETTERS
